



XLuminate Development Kit Getting Started Guide

1 SYSTEM REQUIREMENTS

PC running Windows® 2000 or XP. (Windows® 95, 98, NT, or ME are not supported)

2 PACKING LIST

Part Number	Description
01-20132	XLuminate Lamp/LED Driver
01-20386	XLuminate Development Kit CD
01-20468	Evaluation Board RGB
51-82375	9W D-Type Cable Form
61-20599	34W IDC Cable Form Mirrored
61-20433	XLuminate 5W Power Link
61-20434	XLuminate 4W Power Cable
63-82266	9W M - 9W F Serial Lead 1m
63-82240	USU Cable 2.0M
63-82413	PSU Flex 12V 180W 110-230V
63-82256	Mains Cable

3 INSTALLING THE WINDOWS SOFTWARE

Place the CD in the CD-ROM drive of your PC. The Setup program should run automatically. If the installation does not start, open the CD drive by double-clicking the CD drive icon in 'My Computer', and then double-click the 'Setup' icon. Follow the on screen instructions to complete the installation. It is recommended that you choose the Complete Installation and accept the default install path. This will create a **C:\heber\XLuminate** directory for the installation.